




**COBRA**  
ME1032




It is highly recommended that you visit [www.metalearth.com/360/ME1032](http://www.metalearth.com/360/ME1032) to see the completed model before assembling your own

## ASSEMBLY FLOW CHART


### Step 1



### Step 2



## TO CREATE THE BEST CONNECTIONS



Consider these engraved patterns as supporting features for the bend

### Legends:

- E** Engraved/ Color side
- NE** Non - engraved/ Silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

### Assembly tip:

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish.



- Yellow areas should be curled
- Red areas should be folded

### Recommended tools:


- Wire cutters: helpful for taking parts from the metal sheets.



- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.







## METAL SHEETS









In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.














Step 8

