ICONX

360° view


It is highly recommended that you visit
www.metalearth.com/360/icx023
to see the completed model before assembling your own

Metal Earth
3D METAL MODEL KITS

ICX023 Silver Dragon



TO CREATE THE BEST CONNECTIONS



Legends:


- E — Engraved side
- NE — Non-engraved side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

Assembly tip:


If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

Recommended tools:


-Wire cutters: helpful for taking parts from the metal sheets.




-Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.



ASSEMBLY STEPS








In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.


Go to www.metalearth.com/360/icx023 to see the zoomable PDF version of this instruction sheet


METAL SHEETS












3
E
1



4
E
1



5
E



6
E



2
3
4
5
6



7
E



8
E



7
8



2
E
3
E



4
E
5
E



6
E
7
×2



8



A
E
9 X2
NE



B
E
9 X2
NE



10
E
11
9a
9a
E
9b
9b
E
NE
A
10a
10a
E



12
E
13
NE
14
NE
1
15
NE


E
13
NE
16
14
NE
1



17
NE
FASCINATIONS



Front
C
Front
E
FASCINATIONS



FASCINATIONS
NE
10b
E



FASCINATIONS


FASCINATIONS
11a
E
11a



19
18
NE
E
20
21
NE



22
E



21
E



20
E



19
E



18
E
22






12
E
23
E



13
E
24
FASCINATIONS



14
E
25
FASCINATIONS



15
E
26
FASCINATIONS



16
E
22
FASCINATIONS



11b
E
NE
12
13
14
15
16
FASCINATIONS



17
E
22
FASCINATIONS



B
B1
A1
E



1
E
27
Bend to the shape of part 28
28
a ×2



29
30
31
32
b ×2



33
34
b
a



35
34
b
a



1
E
27
36
Bend to the shape of part 36



37
38
31
39
c ×2


33
E
34
C
E


40
E
1
E
Bend to the shape of part 36
36
E


35
E
C
E
34
41
NE




B2
B2
A2
A2
E
Fascinations®
©2017 Fascinations Seattle, WA
www.metalearth.com