
Metal Earth®

3D METAL MODEL KITS




P-40 WARHAWK

MMS213

360° view

It is highly recommended that you visit
www.metalearth.com/360/mms213
to see the completed model before assembling your own



Insertion tabs are inserted and then folded

Insertion holes

Fold lines can be seen as shown here

Legends:

- E — Engraved / Color side
- NE — Non-engraved / Silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

Assembly tip:


If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

Recommended tools:

-Wire cutters: helpful for taking parts from the metal sheets.




-Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.




Metal sheets

A

Parts that are in the same color are duplicates




B





In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed


Go to www.metalearth.com/360/mms213 to see the zoomable PDF version of this instruction sheet


Assembly Flow Chart












































Fascinations®

© 2020 Fascinations Seattle, WA

www.metalearth.com