Assembly Flow Chart

METAIL EARTH

3D LASER CUT MODELS






It is highly recommended that you visit

www.fascinations.com/metalearth360/mms268

to see the completed model before assembling your own




To create the best connections


mms268




Insert tab and bend 90 degrees for most visible areas




Insert tab and twist 90 degrees is best in some areas to ensure a tight connection





Metal sheets



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

