


Metal Earth®

3D METAL MODEL KITS




Mustang P-51

Item No. MMS003



It is highly recommended that you visit
www.metal-earth.com/360/mms003
 to see the completed model before assembling your own



Insertion
 tabs are
 inserted
 and then
 folded

Insertion holes

Fold
 lines can
 be seen
 as shown
 here

Legends:

- E** Engraved side
- NE** Non-engraved side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

Assembly tip:


If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

Recommended tools:


-Wire cutters: helpful for taking parts from the metal sheets.



-Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.



Metal sheet



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

