





It is highly recommended that you visit www.metal-earth.com/360/icx133 to see the completed model before assembling your own




ICX133 DARTH VADER



TO CREATE THE BEST CONNECTIONS



Consider these engraved stripes as supporting features for the bend



Legends:

- E** Engraved/Color side
- NE** Non-engraved/silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

Assembly tip:


If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

Recommended tools:

-Wire cutters: helpful for taking parts from the metal sheets.




-Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.




METAL SHEETS

A



In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.


B



C




D




ASSEMBLY STEPS


Step 1




Step 2




Step 3





Step 4





Step 5




Step 6




Step 7




Step 8




Step 9




Step 10



Step 11




Step 12




Step 13


Step 12




Step 14




Step 13




Step 15




Step 16




Step 15




Step 17




Step 18




Step 19







Step 20





Step 21





Step 25



Step 26

