


## GREAT WHITE SHARK ME1008

It is highly recommended that you visit [www.metalearth.com/360/ME1008](http://www.metalearth.com/360/ME1008) to see the completed model before assembling your own




### ASSEMBLY FLOW CHART


#### Step 1




#### Step 2



#### Step 3



### TO CREATE THE BEST CONNECTIONS



Consider these engraved stripes as supporting features for the bend

#### Legends:

- Engraved/ Color side
- Non - engraved/ Silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

#### Assembly tip:

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish.


- Yellow areas should be curled
- Red areas should be folded

#### Recommended tools:


- Wire cutters: helpful for taking parts from the metal sheets.




- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.




### METAL SHEETS




Parts with same color are duplicates




In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.




Step 4




Step 5




Step 6




A-21




Step 7




Step 6





Step 8






Step 4




Step 9




Step 10




Step 11






B-37



B-38



Step 12

