

TRICERATOPS ME1011


360°
view




It is highly recommended that you visit
www.metalearth.com/360/ME1011
to see the completed model before assembling your own

TO CREATE THE BEST CONNECTIONS

B
23



Consider these engraved stripes as supporting features for the bend



Legends:

E Engraved/ Color side

NE Non - engraved/ Silver side

Attention point

Insert tab and bend 90 degrees

Insert tab and twist 90 degrees

Assembly tip:

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish.

Yellow areas should be curled

Red areas should be folded


In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.

Recommended tools:

- Wire cutters: helpful for taking parts from the metal sheets.




- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.




METAL SHEETS

A




B




Parts with same color are duplicates

C











ASSEMBLY FLOW CHART









Step 1




Step 2










Step 13



Step 14



Step 15



Step 16

