

F-22[®] RAPTOR[®]
ME1016

It is highly recommended that you visit www.metalearth.com/360/ME1016 to see the completed model before assembling your own



METAL SHEETS

Parts with same color are duplicates

A

B

C

! In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.

TO CREATE THE BEST CONNECTIONS

Consider these engraved stripes as supporting features for the bend

Legends:

- E** Engraved/ Color side
- NE** Non - engraved/ Silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

Assembly tip:

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish.

- Yellow areas should be curled
- Red areas should be folded

Recommended tools:







- Wire cutters: helpful for taking parts from the metal sheets.
- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.

ASSEMBLY FLOW CHART


Step 1

Step 2


Step 3




Step 9





Step 10





Step 11






Step 12







Step 13



Step 14



Step 15



Step 16

