


## ETA-2 JEDI STARFIGHTER™ MMS487

It is highly recommended that you visit  
[www.metalearth.com/360/MMS487](http://www.metalearth.com/360/MMS487)  
to see the completed model before assembling your own




### TO CREATE THE BEST CONNECTIONS

BC - 18



Consider these engraved stripes as supporting features for the bend



#### Legends:

- E** Engraved/ Color side
- NE** Non - engraved/ Silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

#### Recommended tools:

- Wire cutters: helpful for taking parts from the metal sheets.

- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.



#### Assembly tip:

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish.

- Yellow areas should be curled
- Red areas should be folded


### METAL SHEETS

Parts with same color are duplicates




### ASSEMBLY FLOW CHART












#### Step 1













#### Step 2




In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.







Step 16




Step 17



Step 18



Step 19



Step 20

