

Windmill

MMS038

360°
view



It is highly recommended that you visit
www.metalearth.com/360/mms038
to see the completed model before assembling your own


Legends:

- E Engraved side
 - NE Non-engraved side
 - Attention point
 - Insert tab and bend 90 degrees
 - Insert tab and twist 90 degrees
- Assembly tip:**
If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

Recommended tools:

- Wire cutters: helpful for taking parts from the metal sheets.
- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.

Metal sheets



! In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

