


METAL EARTH™


3D LASER CUT MODELS




It is highly recommended that you visit www.fascinations.com/metalearth360/mms312 to see the completed model before assembling your own



mms312



Insertion tabs are inserted and then folded
 Insertion holes
 Fold lines can be seen as shown here




Needle nose pliers are helpful for assembly


Metal sheet

To create the best connections

- Insert tab and bend 90 degrees for most visible areas
- ▲ Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



Pull and Screw metal tab 90° to tighten



⚠ In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

