
3D METAL MODEL KITS








NAOE ARMOR MMS463


It is highly recommended that you visit


www.metalearth.com/360/mms463


to see the completed model before assembling your own

Metal sheets

















Legends: Engraved/Color side








Assembly tip:


If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

Recommended tools:


-Wire cutters: helpful for taking parts from the metal sheets.





-Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.





Assembly Flow Chart



















© 2020 Fascinations Seattle, WA www.metalearth.com

