



METAL SHEETS

Parts with same color are duplicates


A



B



C



Metal Earth

360°
view





It is highly recommended that you visit www.metalearth.com/360/icx231 to see the completed model before assembling your own


Premium Series

ICX231

MONITOR AND MERRIMACK



TO CREATE THE BEST CONNECTIONS



Legends:

- E** Engraved/ Color side
- NE** Non - engraved/ Silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

Recommended tools:

- Wire cutters: helpful for taking parts from the metal sheets.
- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.


Assembly tip:

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish.



In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.

ASSEMBLY STEPS




Step 1




Step 2





Step 3




Step 4





Step 5




Step 6




Step 7




Step 8




Step 14




Step 15




Step 16




Step 17




Step 18




Step 19




Step 20




Step 21




Step 22




Step 23




Step 24




Step 25





Step 26



Step 27



Step 28



Step 29

