


3D METAL MODEL KITS



WORLDVIEW LEGION

MMS490




It is highly recommended that you visit www.metalearth.com/360/MMS490

to see the completed model before assembling your own

Red areas should be folded


TO CREATE THE BEST CONNECTIONS <u>Legends:</u> Recommended tools: Wire cutters: helpful for taking Engraved/ Color side parts from the metal sheets. \mathbf{B} – \mathbf{G} A - 20(NE) Non - engraved/ Silver side Tab Attention point -Tweezers or needle nose pliers: E helpful for folding parts, Insert tab and bend 90 degrees Fold Line bending and twisting tabs. Insert tab and twist 90 degrees Assembly tip: Slot If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish. Consider these engraved stripes as Yellow areas should be curled supporting features for the bend







Page 2

Step 1 B-6 4 B-6 4 Connect the tabe illustrated in red first







Page 3

