


1982 Ford F-150
ME1004

It is highly recommended that you visit www.metalearth.com/360/ME1004 to see the completed model before assembling your own



Ford Motor Company Trademarks and Trade Dress used under license to Fascinations, Inc.

TO CREATE THE BEST CONNECTIONS



Consider these engraved stripes as supporting features for the bend

Legends:

- E** Engraved/ Color side
- NE** Non - engraved/ Silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

Assembly tip:


If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish.

- Yellow areas should be curled
- Red areas should be folded


Recommended tools:

- Wire cutters: helpful for taking parts from the metal sheets.
- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.

METAL SHEETS







Parts with same color are duplicates



In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.

ASSEMBLY FLOW CHART



Step 5

B-14

C-15

C-16

E

Step 2

Step 6

C-17

B-18

B-19

E

Step 3

Step 4

Step 5

Step 7

B-21

C-20

C-22

E

Step 8

B-23

E

Step 9

C-25

A-24

E

Step 10

B-26

AC-27

B-28

B-29

B-30

E

Step 6

Step 7

Step 8

Step 9

Connect the tabs illustrated in red first

Connect the tabs illustrated in red first

Rotate

Step 11

C-31

B-32

A-33

E

