


## F-16 FIGHTING FALCON® ME1046



It is highly recommended that you visit [www.metalearth.com/360/ME1046](http://www.metalearth.com/360/ME1046) to see the completed model before assembling your own



### TO CREATE THE BEST CONNECTIONS



**Legends:**

- E** Engraved/ Color side
- NE** Non - engraved/ Silver side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

**Assembly tip:**  
If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish.


- Yellow areas should be curled
- Red areas should be folded

**Recommended tools:**

- Wire cutters: helpful for taking parts from the metal sheets.
- Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.

### METAL SHEETS


Parts with same color are duplicates




In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed.


### ASSEMBLY FLOW CHART

#### Step 1




#### Step 2








**Step 3**




**Step 4**




**Step 5**




**Step 6**




**Step 7**







Step 8









Step 9




Step 10





Step 11







Step 13




Step 14






Step 12





Step 15




Step 16




Step 17



Step 18



Step 19



Step 20

