3D LASER CUT MODELS







It is highly recommended that you visit www.fascinations.com/metalearth360/mms323 to see the completed model before assembling your own










Metal sheets


To create the best connections




Insert tab and bend 90 degrees for most visible areas




Insert tab and twist 90 degrees is best in some areas to ensure a tight connection







In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed



Assembly Flow Chart

