


# METAL EARTH®

## 3D METAL MODEL KITS

Page 1



It is highly recommended that you visit  
[www.fascinations.com/metalearth360/mms376](http://www.fascinations.com/metalearth360/mms376)  
 to see the completed model before assembling your own



mms376

Insertion tabs are inserted and then folded

Fold lines can be seen as shown here

Insertion holes

Needle nose pliers are helpful for assembly

Legends:


- E** Engraved side
- NE** Non-engraved side
- Attention point

**To create the best connections**

- Insert tab and bend 90 degrees for most visible areas
- Insert tab and twist 90 degrees is best in some areas to ensure a tight connection

Pull and Screw metal tab 90° to tighten

### Metal sheets



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

### Assembly Flow Chart

Page 2

